

Day : Friday  
Date: 9/15/2006

Time: 13:13:08

 **PALM INTRANET****Inventor Name Search Result**

Your Search was:

Last Name = WILDENHAIN

First Name = KLAUS

Application#	Patent#	Status	Date Filed	Title	Inventor Name
<a href="#">09396788</a>	<a href="#">6574929</a>	150	09/15/1999	FIRE-RESISTANT ELEMENT FOR THE CLOSURE OF A ROOM	WILDENHAIN, KLAUS
<a href="#">10018728</a>	<a href="#">6787214</a>	150	12/18/2001	FIRE-INHIBITING FLAT ELEMENT COMPRISING AT LEAST TWO TRANSPARENT FIRE-RESISTING GLASS PLATES	WILDENHAIN, KLAUS
<a href="#">10072002</a>	Not Issued	71	02/12/2002	Fixing for composite glazing	WILDENHAIN, KLAUS

**Inventor Search Completed:** No Records to Display.

**Search Another: Inventor**

<b>Last Name</b>	<b>First Name</b>	
<input type="text" value="WILDENHAIN"/>	<input type="text" value="KLAUS"/>	<input type="button" value="Search"/>

To go back use Back button on your browser toolbar.

Back to [PALM](#) | [ASSIGNMENT](#) | [OASIS](#) | [Home page](#)

Day : Friday  
Date: 9/15/2006

Time: 13:13:33

**PALM INTRANET****Inventor Name Search Result**

Your Search was:

Last Name = LINDEN

First Name = RALF

Application#	Patent#	Status	Date Filed	Title	Inventor Name
<a href="#">08678021</a>	<a href="#">5698277</a>	150	07/10/1996	FIRE-RESISTANT GLAZING	LINDEN, RALF
<a href="#">09396788</a>	<a href="#">6574929</a>	150	09/15/1999	FIRE-RESISTANT ELEMENT FOR THE CLOSURE OF A ROOM	LINDEN, RALF
<a href="#">10072002</a>	Not Issued	71	02/12/2002	Fixing for composite glazing	LINDEN, RALF

**Inventor Search Completed: No Records to Display.**

**Search Another: Inventor**

<b>Last Name</b>	<b>First Name</b>	
<input type="text" value="LINDEN"/>	<input type="text" value="RALF"/>	<input type="button" value="Search"/>

To go back use Back button on your browser toolbar.

Back to [PALM](#) | [ASSIGNMENT](#) | [OASIS](#) | [Home page](#)

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	27	(FIRE SAME RESISTANT SAME GLAZING)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:14
L2	14	(GLAZING SAME SAFETY SAME SUPPORT)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:15
L3	67	(GLAZING SAME FIRST SAME SECOND SAME PANE)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:39
L4	53	(GLAZING SAME FIRST SAME SECOND SAME POSITION)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:40
L5	0	(GLAZING SAME FIRST SAME SECOND SAME CONTACTING SAME MEMBER)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:40
L6	13	(GLAZING SAME CONTACTING SAME MEMBER)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:41
L7	0	(GLAZING SAME CONTACTING SAME SAFETY SAME MEMBER)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:41
L8	0	(GLAZING SAME CONTACTING SAME SAFETY)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:41
L9	0	(GLAZING SAME CONTACTING SAME SAFETY SAME SUPPORT)".CLM"	US-PGPUB	OR	OFF	2006/09/15 13:47
L10	73	(52/235).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:47
L11	38	(52/506.05).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:47
L12	5	(52/508).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:47
L13	7	(52/512).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:47
L14	1	(403/26).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:47
L15	0	(403/77).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:48
L16	7	(403/78).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:48
L17	0	(403/115).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:48
L18	0	(403/117).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:48
L19	33	(403/135).CCLS.	US-PGPUB	OR	OFF	2006/09/15 13:48